# Oil Field Environmental Incident Summary

Responsible Party: MBI Energy Services

Well Operator: MARATHON OIL COMPANY

Well Name: VERLYN STROMMEN 34-8H

Field Name: KILLDEER Well File #: 20450

Date Incident:11/30/2015Time Incident:09:32Facility ID Number:County:DUNNTwp:145Rng:94Sec:8Qtr:

Location Description:

Submitted By: Nathan Ehlis Received By:

Contact Person: Nathan Ehlis

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 1.2 barrels 1.2 Barrels 1.2 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 12/9/2015 Clean Up Concluded: 12/1/2015

Risk Evaluation:

No risk

Areal Extent:

The entire spill was contained within the tank farm berm.

## Potential Environmental Impacts:

No impacts, the spill was contained within the tank farm berm.

## Action Taken or Planned:

The spill was caused by driver error. The driver will be re-trained before being allowed to go back to work.

**Wastes Disposal Location:** All contaminated materials will be taken to the R360 waste disposal in Fairfield ND.

Agencies Involved:

## **Updates**

Date: 12/1/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to a valve/piping connection leak, remained within diking according to the report. NDIC retains oversight.